

FACILITY CONDITION ASSES


Jordan ES| February 2022



M μ μ μ μ ^ ž U : } • îìîî 1







Executive Summary

Jordan ES is located at 6711 Johnny Morris Rd in Austin, Texas. The oldest building is 28 years old (at time of 2020 assessment). It comprises 76,113 gross square feet.

The findings contained within this report are the result of an assessment of building systems and the conditions found on the site at the time of the visit. The assessment was performed by building professionals experienced in disciplines including architecture, mechanical, plumbing and electrical. The total current deficiencies for this site, in 2020 construction cost dollars, are estimated at \$1,663,743. A ten-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Jordan ES the ten-year need is \$8,266,173.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined to calculate a Facility Condition Assessment (FCA) score. A 5-year FCA was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCA calculation. The Jordan ES facility has a 5-year FCA score of 71.76%.

Summary of Findings


The table below summarizes the condition findings at Jordan ES


Table 1: Facility Condition by Building




Number

Building Name







Life Cycle Capital Renewal Forecast

'XULQJ WKH IDFLOLW\ FRQGLWLRQ DVVHVVPHQW DVVHDVQRDWVHQV\$HUFMGH for immediate replacement, a deficiency was created with the item's repair costs. The identified deficiency contributes to the facility's total current repair costs.




Table 3b: Capital Renewal Forecast (Yrs 6-10)

		Life Cycle Capital Renewal Projections						
System	Total 1-5	Year 6 2028	Year 7 2029	Year 8 2030	Year 9 2031	Year 10 2032	Total 6-10	Total 1-10
Site	\$459,327	\$0	\$0	\$107,609	\$0	\$0	\$107,609	\$566,936
Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$154,961	\$0	\$14,828	\$0	\$0	\$74,140	\$88,968	\$243,929
Interior	\$1,326,763	\$82,725	\$0	\$17,590	\$0	\$625,233	\$725,548	\$2,052,311
Mechanical	\$2,437,463	\$0	\$0	\$0	\$0	\$29,279	\$29,279	\$2,466,742
Electrical	\$113,870	\$5,969	\$0	\$87,316	\$0	\$0	\$93,285	\$207,155
Plumbing	\$436,979	\$0	\$0	\$6,384	\$0	\$7,235	\$13,619	\$450,598
Fire and Life Safety	\$0	\$0	\$0	\$0	\$155,192	\$0	\$155,192	\$155,192
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$464,623	\$0	\$0	\$0	\$0	\$0	\$0	\$464,623
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$5,393,986	\$88,694	\$14,828	\$218,899	\$155,192	\$735,887	\$1,213,500	\$6,607,486







Figure 2: Ten Year Capital Renewal Forecast

 $M_{APP}P_{\mu}^{A} \stackrel{\mathsf{z}}{\cup} : \quad \} \quad \bullet \quad \hat{\mathsf{i}} \hat{\mathsf{i}} \hat{\mathsf{i}}$










Facility Condition Assessme

Austin ISD - Jordan

Plumbing

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Electric - 5 to 10 gallon		1	Ea.	\$1,264	10
		Sub Total for System	5	items	\$71,337	
Fire and Life Safety						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Fire Detection and Alarm	Fire Alarm		13,713	SF	\$21,774	9
Fire Detection and Alarm	Fire Alarm Panel		1	Ea.	\$6,868	9
		Sub Total for System	2	items	\$28,642	
Specialties						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Casework	Fixed Cabinetry		12	Room	\$105,622	2
		Sub Total for System	1	items	\$105,622	
	Sub Total for Building 178B - Stand	ding 178B - Stand-Alone Classroom Building 19 items \$759.	\$759,308			
		Total for: Jordan ES	76	items	\$6 607 487	

M A P P μ ^ ž U : } • î ì î î 12



Supporting Photos

General Site Photos

