FACILITY CONDITION ASSES

Rodriguez ES | February 2022

Executive Summary

The following table summarizes this site's current deficiencies by building system and priority.

Table 2: System by Priority (Site & Permanent Buildings)

	Priority						
System	1	2	3	4	5	Total	% of Total
Site	$0	$0	$0	$0	$531,52	$531,52	28.60 %
Roofing	$0	$0	$0	$0	$0	$0	0.00 %
Structural	$0	$0	$0	$0	$0	$0	0.00 %
Exterior	$0	$0	$0	$0	$0	$0	0.00 %
Interior	$0	$0	$0	$0	$0	$0	0.00 %
Mechanical	$0	$612,75	$102,84	$36,57	$0	$752,18	40.48 %
Electrical	$0	$0	$0	$0	$0	$0	0.00 %
Plumbing	$0	$3,79	$6,38	$29,40	$0	$39,58	2.13 %
Fire and Life Safety	$535,04	$0	$0	$0	$0	$535,04	28.79 %
Conveyances	$0	$0	$0	$0	$0	$0	0.00 %
Specialties	$0	$0	$0	$0	$0	$0	0.00 %
Crawlspace	$0	$0	$0	$0	$0	$0	0.00 %
Total:	$535,04	$616,55	$109,23	$65,98	$531,52	$1,858,33	

The building systems at the site with the most need include:

Mechanical	-	$752,180
Fire and Life Safety	-	$535,048
Site	-	$531,524